

Download Merc 115 Manual Trim Lock

14 Nitro Z7 14 175 Merc Pro XS Listed 3/7/19: 24 Tempest Plus, 6" manual jackplate, MinnKota iPilot with spot lock and remote, Humminbird 9 w/Side/Down imaging on Ram mount, Lowrance 5" indash, 2 digital chargers. 17 Legend V20 17 250 Merc Pro XS Listed 12/31/18P: Black Bob's hydraulic w/gauge, MK Ultrex 112#, 2 HB Helix 12's DI and Mega DI/SI linked on DekIt mounts, 8' Power Pole Blades, 2 indash digital boat gauges, 4 new batteries, 4 bank charger, Kicker sound system, dual pro trim, hot foot, keel guard, new travel cover, custom wheels with low miles on tires. I have a Volvo DPE stern drive with Volvo power trim 3860880 motor/pump. The Trim unit works OK when boat out of water and stationary in water (leg travels full length of clean piston rams) but when underway, the pump/motor makes a hammering noise when lowering leg – this noise does not occur when lifting the leg. Tilt and Trim Motor Replacing Power Trim and Tilt Systems. When replacing your Power Tilt and Trim Motor, first identify what type of Power Tilt and Trim Motor and Pump you have in your boat.